


Image Report

Project: Hampden Mall Roof

Session: Raw Data

Image: 0012_IR8000

Project	Hampden Mall Roof	Time	01:29:56
Company	ABC. Inc	Emissivity	0.9
Contact	John Smith	Ambient	50 F
Address 1	1234 Main Street	Humidity	40%
City	Denver	GPS Latitude	39° 39' 6.78" N
State	CO	GPS Longitude	104° 52' 57.58" W
Zip	80202	GPS Altitude	1808.491943
Date	2018:03:09	GPS Heading	277.420013



Annotation: Membrane Hotspot



Comment	Anomaly indicative of roof membrane degradation.
Probable Cause	Excessive exhaust heat.
Recommendation	Perform visual inspection on membrane.